

APPENDIX B



B.1.a. Terminal outfall MNWA01 post



B.1.b Terminal outfall MNWA01 flooded by Menomonee River after heavy



B.2.a New 12-foot diameter stormwater lines were laid along 90th Street during the Meinecke Avenue Utility Reconstruction



B.2.b New sanitary pipe was laid along 90th Street. Photograph shows native clay material below the asphalt surface along the trench walls and chipped granular crushed limestone backfilling the sanitary trench. New residential lateral hook-ups are also visible.

Figure B.2 Appendix B



B.3.a. Monitoring wells MW-1 and MW-2 located within the intersection of Wright Street and 83rd Street facing north. A sanitary manhole is visible to the east of MW-1 and south of MW-2.



B.3.b. MW-3 is located at the intersection of Wright and 86th Street. MW-3 is located southwest of a sanitary manhole visible in the center of the photograph.